



Leistungs- und Drehmomentdiagramm
Power- and Torque-Diagram
Diagramme de puissance et couple

HT 30.1 S 80

Leistung
Power
Puissance



Drehmoment
Torque
Couple



Werte
Values
Valeurs

		n x 1000 [rpm]	20	40	60
P [W]	S1		105	200	280
	S6-40%		136.5	260	364
M [Ncm]	S1		5	4.8	4.5
	S6-40%		6.5	6.2	5.8

B40-180

Wärmeableitung muss über den Spindelhalter erfolgen; max. Gehäusetemperatur 60°C
Heat must be dissipated via spindle holder; max. external housing temperature 60°C

La dissipation de chaleur doit se faire à travers le support de broche; Température max. du corps 60°C