



Leistungs- und Drehmomentdiagramm
Power- and Torque-Diagram
Diagramme de puissance et couple

HT 22 D/S 100 P

Leistung
Power
Puissance



Drehmoment
Torque
Couple



Werte
Values
Valeurs

	n x 1000 [rpm]	20	60
P [W]	S1	74	180
	S6-40%	98	234
M [Ncm]	S1	3.5	2.8
	S6-40%	4.7	3.7

B40-007